

Máquinas Lava-roupas – Cinza

Indicadas especialmente para utilização em máquinas lavadoras de roupa. Extremamente flexível e com a parede interna lisa. Fornecida em rolos ou em peças montadas com a respectiva luva.

Temperatura de Trabalho: +5°C ~ +50°C (PVC).

DIÂMETRO NOMINAL	DIÂMETRO INTERNO	DIÂMETRO EXTERNO	PRESSÃO DE TRABALHO		PRESSÃO DE RUPTURA		VÁCUO	RAIO DE CURVATURA	LANCE
			25°C		25°C		25°C	Trabalho - Mínimo	
								25°C	
pol.	mm	mm	kgf/cm2	lbf/pol2	kgf/cm2	lbf/pol2	mmHg	mm	m
1"	25,0	29,2	2,0	28	6,0	85	550	60	50



Lavadoras – Gris

Adecuada especialmente para uso en máquinas de lavarropas. Extremamente flexible y pared interior lisa. Se suministra en rolos o piezas montadas con el conector correspondiente.

Temperatura de Trabajo: +5°C ~ +50°C (PVC).

DIÂMETRO NOMINAL	DIÂMETRO INTERNO	DIÂMETRO EXTERNO	PRESIÓN DE TRABAJO		PRESIÓN DE RUPTURA		VACÍO	RADIO DE CURVATURA	LARGO
			25°C		25°C		25°C	Trabajo - Mínimo	
								25°C	
pul.	mm	mm	kgf/cm2	lbf/pul2	kgf/cm2	lbf/pul2	mmHg	mm	m
1"	25,0	29,2	2,0	28	6,0	85	550	60	50



Washing Machines – Gray

Specially recommended for use in washing machines. Extremely flexible and with glossy inner wall. Supplied in rolls or pieces with the respective fitting.

Working Temperature: +5°C ~ +50°C (PVC).

NOMINAL DIAMETER	INTERNAL DIAMETER	EXTERNAL DIAMETER	WORK PRESSURE		BURST PRESSURE		VACUUM	BEND RADIUS	LENGTH
			25°C		25°C		25°C	Working - Minimum	
								25°C	
inches	mm	mm	kgf/cm2	psi	kgf/cm2	psi	mmHg	mm	m
1"	25,0	29,2	2,0	28	6,0	85	550	60	50

